## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078132
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	50 . 3 ban
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	7-2
	8. FARM OR LEASE NAME 2 SAP #
1. oil gas 🛣 other	A. L. Elliott "A"
	9. WELL NO.
2. NAME OF OPERATOR	3
AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Pictured Cliffs
501 AIRPORT DRIVE, FARMINGTON, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA DEST REPORTED
below.)	NE/4 NE/4 Sec. 11, T29N, R9W
AT SURFACE:1165 FNL x 1120 FEL, Sec. 11, T29N,	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same R9W	San Juan - New Mexico
AT TOTAL DEPTH: Same	14. API NO. 1. 5 1. 5 1. 2. 30-045-22927
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-045-2292₹∄∄ g falls
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6324' GL 🔞 📆 🖟 🖟 🖟 🖟 🗸 🗸
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	그는 그는 그를 하는 것이 얼마를 하는 것이 없다면 하는 것이 없다면 하는 것이다.
REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	다 나는 사람들이 다 다 다 다 다 다 다 다 다 다 다 다 다 다 다 다 다 다 다
ABANDON*	Control of the contro
(other) Spud and set casing	
	<u> </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.	irectionally drilled, give subsurface locations and
Spudded 12-1/4" hole 4/10/78. Drilled to 273',	
271'. Cemented with 260 sx Class "B", 2% CaCl <sub>2</sub> .	
30 minutes. Drilled 7-7/8" hole to total depth	of 3160' ran 4-9/2" 10 5# 4-55
casing, landed at 3159, cemented with 625 sx Cla	18" 50 50 50 67 651 38 4 Mod
Tuf Plug/sx, followed with 100 sx Class "B". Di	
int itabley tottowed with too by order b . 101	who circulates

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: **REQUEST FOR APPROVAL TO:** TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other) Spud and set casing 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s including estimated date of starting any proposed work. If well i measured and true vertical depths for all markers and zones perti Spudded 12-1/4" hole 4/10/78. Drilled to 273 271'. Cemented with 260 sx Class "B", 2% CaC 30 minutes. Drilled 7-7/8" hole to total dept casing, landed at 3159, cemented with 625 sx Tuf Plug/sx, followed with 100 sx Class "B". Rig released 4/14/78. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct ್ರಾಡ By TITLE Area Adm. Supervisor SIGNED. OZODA (This space for Federal or State office use) TITLE DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: