

*Denny S. Faust*  
DEPUTY OIL & GAS INSPECTOR

DEC 30 1997

*Approved*

Meter Number:90774  
Location Name:FLORANCE #57R  
Location:TN-29 RG-09  
SC-22 UL-A  
2 - Federal  
NMOCD Zone:OUTSIDE  
Hazard Ranking Score:00

RECEIVED  
APR 1 1997  
OIL CONSERV. DIV.  
PAGE 2

**RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS  
LOCATED OUTSIDE OF THE VULNERABLE ZONE  
IN THE SAN JUAN BASIN**

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone	$10^{-9}$ to $10^{-13}$ cm/sec
Shale	$10^{-12}$ to $10^{-16}$ cm/sec
Clay	$10^{-12}$ to $10^{-15}$ cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM



**GENERAL**

Meter: 90774 Location: FLORENCE # 57-R  
 Operator #: 0203 Operator Name: Amoco P/L District: BLANCO  
 Coordinates: Letter: A Section 22 Township: 29 Range: 9  
 Or Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
 Pit Type: Dehydrator \_\_\_\_\_ Location Drip:  Line Drip: \_\_\_\_\_ Other: \_\_\_\_\_  
 Site Assessment Date: 5.13.94 Area: 13 Run: 22

**SITE ASSESSMENT**

**NMOCD Zone:** (From NMOCD Maps) Inside  (1) Outside  (2)

**Land Type:** BLM  (1) State  (2) Fee  (3) Indian \_\_\_\_\_

**Depth to Groundwater**  
 Less Than 50 Feet (20 points)  (1)  
 50 Ft to 99 Ft (10 points)  (2)  
 Greater Than 100 Ft (0 points)  (3)

**Wellhead Protection Area :**  
 Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source?  (1) YES (20 points)  (2) NO (0 points)

**Horizontal Distance to Surface Water Body**  
 Less Than 200 Ft (20 points)  (1)  
 200 Ft to 1000 Ft (10 points)  (2)  
 Greater Than 1000 Ft (0 points)  (3)

Name of Surface Water Body \_\_\_\_\_  
 (Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)  
 Distance to Nearest Ephemeral Stream  (1) < 100' (Navajo Pits Only)  
 (2) > 100'

**TOTAL HAZARD RANKING SCORE: 0 POINTS**

**REMARKS**


Remarks : ~~FLORENCE # 57-R~~ <sup>5.13.94</sup> TWO PITS ON LOCATION. WILL CLOSE ONLY ONE PIT IS DRY. LOCATION IS ON A HILL NORTH OF LARGO WASH. PROLINE ~~SHOWS~~ <sup>5.13.94</sup> AND TOPO CONFIRMED LOCATION TO BE OUTSIDE U.Z.

**PUSH IN**

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 356° Footage from Wellhead 83'  
b) Length : 21' Width : 18' Depth : 2'

ORIGINAL PIT LOCATION



REMARKS

Remarks :

TOOK PICTURES AT 10:24 A.M.  
END OUMP

Completed By:

Robert Thompson  
Signature

5.13.94  
Date

## FIELD PIT REMEDIATION/CLOSURE FORM

<b>GENERAL</b>	Meter: <u>90774</u> Location: <u>Florence #57-R</u> Coordinates: Letter: <u>A</u> Section <u>22</u> Township: <u>29</u> Range: <u>9</u> Or Latitude _____ Longitude _____ Date Started : <u>7-18-94</u> Run: <u>13</u> <u>22</u>
<b>FIELD OBSERVATIONS</b>	Sample Number(s): <u>MK 147</u> Sample Depth: <u>4'</u> Feet Final PID Reading <u>199</u> PID Reading Depth <u>4'</u> Feet Groundwater Encountered <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Approximate Depth _____ Feet
<b>CLOSURE</b>	Remediation Method : Excavation <input type="checkbox"/> Approx. Cubic Yards _____ Onsite Bioremediation <input type="checkbox"/> Backfill Pit Without Excavation <input checked="" type="checkbox"/> Soil Disposition: Envirotech <input type="checkbox"/> Tierra <input type="checkbox"/> Other Facility <input type="checkbox"/> Name: _____ Pit Closure Date: <u>7-18-94</u> Pit Closed By: <u>BEI</u>
<b>REMARKS</b>	Remarks : <u>EPNE lines not marked Soil Gray Slight</u> <u>Hydrocarbon odor H.T Sand Stone 4'</u>
	Signature of Specialist: <u>Morgan Killian</u>



**FIELD SERVICES LABORATORY  
ANALYTICAL REPORT  
PIT CLOSURE PROJECT - Soil**

**SAMPLE IDENTIFICATION**

	Field ID	Lab ID
SAMPLE NUMBER:	mk 147	945701
MTR CODE   SITE NAME:	90774	N/A
SAMPLE DATE   TIME (Hrs):	7/18/94	1119
SAMPLED BY:	N/A	
DATE OF TPH EXT.   ANAL.:	7/19/94	7/19/94
DATE OF BTEX EXT.   ANAL.:	N/A	N/A
TYPE   DESCRIPTION:	VE	lt. Brown fine sand

REMARKS:

**RESULTS**

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	1090	MG/KG			2.01	28
HEADSPACE PID	199	PPM				
PERCENT SOLIDS	22.5 <del>22.5</del>	%				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at N/A % for this sample All QA/QC was acceptable.  
Narrative:

DF = Dilution Factor Used

8/8/94

\*\*\*\*\*  
Test Method for  
Oil and Grease and Petroleum Hydrocarbons  
in Water and Soil  
Perkin-Elmer Model 1600 FT-IR  
Analysis Report  
\*\*\*\*\*

24/07/19 15:22

Sample identification  
745701

Initial mass of sample, g  
1.010

Volume of sample after extraction, ml  
16.000

Petroleum hydrocarbons, ppm  
092.226

Net absorbance of hydrocarbons (2930 cm<sup>-1</sup>)  
1.137

