District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
Strict III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

GLONSERVATION DIVISION

P.O. Box 2088
SEP 2001
RECEIVED
OILOON DIV

SUBMIT 1 COPY TO APPROPRIATE DISTRICT OFFICE AND 1 COPY TO SANTA FE OFFICE

PIT REMEDIATION AND CLOSURE REPORT

Operator:	Amoco Production Company	Telephone: (505) - 326-9200
Address:	200 Amoco Court, Farmington	, New Mexico 87401
Facility Or: ELLIOT, ANNIEL. B # 5E Well Name		
Location: Unit or Qtr/Qtr Sec P Sec O T29N R 9W County SAN JUAN		
Pit Type: Separator X Dehydrator Other		
Land Type: BLM_X, State, Fee, Other		
Pit Location: (Attach diagram)	Reference: wellhead X , other	
	Footage from reference:	125
	Direction from reference	e: 50 Degrees X East North Y
		of West South
Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)		Less than 50 feet (20 points) 50 feet to 99 feet (10 points) Greater than 100 feet (0 Points) 20
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)		Yes (20 points) No (0 points)
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)		Less than 200 feet (20 points) 200 feet to 1000 feet (10 points) Greater than 1000 feet (0 points)
		RANKING SCORE (TOTAL POINTS): 20