


(SUBMIT IN TRIPLICATE)



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 072458
Unit San Juan 30-4 Unit
14-03-001-1036

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 15, 1958

Well No. 27 is located 1700 ft. from N line and 500 ft. from E line of sec. 31
1/4 Sec. 31 (1/4 Sec. and Sec. No.) 30N (Twp.) 4W (Range) N.M.P.M. (Meridian)
Blanco M. V. (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)


The elevation of the derrick floor above sea level is 7503 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-24-58 Total depth 7003'.
Run 16 joints 2 1/2", 15.5#, J-55 casing (2479') set from 4523'
to 7002' with 125 sacks regular cement, 125 sacks Pozulx, 125 Gal,
followed by 50 sacks regular cement.
Hold 1000' for 30 minutes.

Top of cement by temperature survey at 5160'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 107

Fortington, New Mexico

Original Signed By:

By D. W. Meehan

Title Petroleum Engineer