



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Betty Rivera**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
Oil Conservation Division

August 21, 2002

Dolores Silseth  
Burlington Res O&G Co  
PO Box 4289  
Farmington NM 87499

Re: San Juan 30-6 #101, H-35-30N-07W, API# 30-039-07731

Dear Dolores:

The 2002 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before October 20, 2002.

Reference RBDMS CTP0223253105 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: Well file  
CP