

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY El Paso Natural Gas Company, Box 997, Farmington, New Mexico
(Address)

LEASE Barron-K144 WELL NO. 1-F UNIT N S 28 T 30N R 6W

DATE WORK PERFORMED 4-28-57 POOL Blanco

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Abandon

Detailed account of work done, nature and quantity of materials used and results obtained.

4-28-57. Total Depth 70'.

Cable tools attempted to drill surface hole and set surface casing. Hole caved in and stuck bailer in hole. Hole was abandoned and then filled in with dirt and graded over by maintainer.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day


Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____



(Company)

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold

Title Supervisor Dist. # 3

Date MAY 31 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name De Pluster

Position Petroleum Engineer

Company El Paso Natural Gas Company

OIL CONSERVATION COMMISSION

AZTEC DISTRICT OFFICE

No. Copies Received

6

DISTRIBUTION

	NO. COPIES TO	
FOR	4	
STAFF	1	
RECORDS		
OTHER		