

(SUBMIT IN TRIPLICATE)

Land Office San Antonio

Lease No. 080712

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

JAN 4 1952

SUNDRY NOTICES AND REPORTS ON WELLS

GEOLOGICAL SURVEY
FARMINGTON, N. M.

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Abraham 2160' _____, 19 51
Well No. 1 is located 480' ft. from N line and 480' ft. from W line of sec. 27
NW 1/4 SW 1/4
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcat Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well spaced 11-10-51.

205' - 1 1/4" surface pipe at 217' with 175 sacks cement.
Cement circulated. Pipe tested with 1000# prior to
drilling out. Held for 1 hour with no decrease in pressure.
drilled shoe and held 600# pressure for 30 minutes with
no decrease in pressure. Resumed drilling.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barron Kidd

Address 2106 Mercantile Bank Bldg Dallas, Texas

By [Signature]

Title Supt.

