



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 080711
Unit San Juan 30-6 Unit
14-08-001-538

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 30, 19 58

Well No. 26 is located 1150 ft. from NEX line and 290 ft. from W line of sec. 19
SW Sec. 19 30N 6W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On 4-29-58. Total Depth 3365'.
 Ran 81 joints 7 5/8", J-55, 26.40#, casing (3352') set at 3362' with 75 sacks regular cement, 75 sacks Pozmix, 50# Floccle and 4# Gel, followed with 50 sacks Neat cement, with 2# CaCl.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 2150'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Paso Natural Gas Company

Address Box 977

Farmington, New Mexico

By ORIGINAL SIGNED H.E. McWALLY

Title Petroleum Engineer