

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name San Juan 30-5 Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name San Juan 30-5 Unit
3. Address of Operator Box 990, Farmington, New Mexico - 87401	9. Well No. 21 (P&A)
4. Location of Well UNIT LETTER K 1650 FEET FROM THE South LINE AND 1700 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 30N RANGE 5W NMPM.	10. Field and Pool, or Wildcat Blanco Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 7030' GL	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Because of non-production this well has been plugged and abandoned as follows:

Could not unseat packer at 5776', spotted a 50 sack cement plug under packer.


Pulled tubing to 3000', spotted a 200 sack cement plug to cover corroded casing, pulled tubing.

Shot 7 5/8" casing off at 1000', spotted a 50 sack cement plug on casing stub, pulled casing.

Spotted a 25 sack cement plug at base of surface casing.

Spotted a 15 sack cement plug at surface w/a 4' x 4" P & A marker on 5-17-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____	TITLE Petroleum Engineer	DATE 5-22-69
APPROVED BY 	TITLE SUPERVISOR DIST. #3	DATE MAY 26 1969
CONDITIONS OF APPROVAL, IF ANY:		

