Form (Feb	9-3 8 1951 .	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR

App	proval expires 12-31-60.	
d Office	Santa Pe	

Lease No. 079405-B

Unit San Juan 30-4 Unit

			GICAL SURVEY	rierior 1	4	
						LVET
	SUNDRY	NOTICES A	ND REPO	RTS ON	WELLS COM	LO 1957
			SUBSEQUENT RE	EPORT OF WATER S	HUT-OFF	- ''
		PLANS	SUBSEQUENT RE		G OR ACIDIZING	
		TER SHUT-OFF	SUBSEQUENT RE	PORT OF ALTERING	CASING	
		OR REPAIR WELL	SUBSEQUENT RE	PORT OF RE-DRILL	ING OR REPAIR	
		R ACIDIZE	SUBSEQUENT RE	PORT OF ABANDON	MENT	
	NTENTION TO PULL OR NTENTION TO ABANDON	ALTER CASING		WELL HISTORY	~	
		WELL	Water P	rac.		<u>X</u>
	(INDIC	ATE ABOVE BY CHECK MARK	NATURE OF REPORT, N	OTICE, OR OTHER D	ATA)	
			<u></u>	December 5		. 19 57
Well No	17 is loca	ted 950 ft. from				
NE Sec. 1			her		line of sec	. 17
(⅓ Sec.	and Sec. No.)	30N (Twp.) (F	Range)	(Meridian)		
Bast Bler	nco P. C.	Rio Arri	ba		Mexico	
((Field)	(County or	Subdivision)		tate or Territory)	
he elevation	on of the derrick	floor above sea leve				
itate names of	and avacated de-st.	DETAIL	S OF WORK			
11-23-57 11-23-57	Water fract 4369-4392 w max. pr. 24 6,231 gallo Total Depth Temporary E 4107-4149 w max. pr. 15	objective sands; show sizes, ing points, and all oth 4451'. C.O.T.D ured Pictured Cl./34,867 gallons of 50¢, avg. tr. pros. Dropped one 4451'. Pat 4200'. Water 34,500 gallons of 50¢, avg. tr. propped one set of	. 4410'. iffs perf. i water and 35 . 1650, 2200 set of 20 b er fraced. P water and 35 . 1400. 1500	nt. 4283-4; ,000# send. , 2400#.] alls for 2 . C. perf. ,000# send.	301, 4309-435 BD pr. 185 IR 46 BPM. P stages. int. 4075-40 BD pr 1250	1, 6#, 1ush 93,
	El Paso Hate	must receive approval in wri	ting by the Geologica	al Survey before ope	erations marrie From	(S
	Farmington,	New Mexico	R_{v}	Original Sig	gned D. C. Joh	ns.on
			Б у			
			Title	letroleum	Engineer	