



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 079483-A
Lease No. San Juan 30-4 Unit
Unit 14-08-001-1056

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	JUN 16 1958	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER.....	U.S. Geological Survey	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OF.....	FARMINGTON, NEW MEXICO	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 11, 1958

Well No. 24 is located 1650 ft. from XXXX line and 990 ft. from W line of sec. 9
SE Sec. 9 30N 4W H.M.P.M.
 (Field) (Twp.) (Range) (Meridian) New Mexico
 (County or Subdivision) (State or Territory)
East Blanco P.C. Rio Arriba

The elevation of the derrick floor above sea level is 7474 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

June 4, 1958, Total depth 4583'.
 Ran 145 joints, 5 1/2", 15.50#, 4-55 casing (4572') set at 4583' with 75 sacks
 regular cement, 75 sacks Fomix, 2 1/2 gal, 30# Flocalc, followed by 50 sacks
 regular cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 3950'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997
Farmington, New Mexico

By Original Signed D. C. Johnston
Title Petroleum Engineer