(other)

HAITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	SF 079001 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME NEBU Agrmt. No. 1, Sec. 929 8. FARM OR LEASE NAME Northeast Blanco Unit 9. WELL NO. 8 10. FIELD OR WILDCAT NAME Blanco Mesaverde 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA K-10-30N-7W 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6263 GL	
SUNDLY ROTICES ARD REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.) 1. oil 673 888 97		
well LJ well LXJ other 2. NAME OF OPERATOR		
Blackwood & Nichols Co., Ltd. 3. ADDRESS OF OPERATOR P.O. Box 1237, Durango, Co. 81301 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1650' F/SL - 1650' F/WL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA. REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9~330.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pull 2 3/8" tubing, set bridge plug in $5\frac{1}{2}$ " liner; locate holes in 7" casing, repair by squeeze cementing. Drill $5\frac{1}{2}$ " bridge plug, rerun 2 3/8" tubing and return well to production.

		NOV 1 S 1979	2
Subsurface Safety Valve: Manu.	• •	· · · · · · · · · · · · · · · · · · ·	Set @ Ft.
18. I hereby certify that the fore	egoing is true and correct / Lasso Loos TITLE Distr	ict Manager DATE 11-8-	-79
	(This space for Fede	eral or State office use)	:
APPROVED BY		DATE	