

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 072001-A -----

Unit **Northeast Blance**

Unit Agreement No. 1. Sec. 929

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 21, 1956

Well No. 1-B is located 1120 ft. from N line and 1650 ft. from E line of sec. 10

Eu/4 H-14 Section 16
(1/4 Sec. and Sec. No.)

302
(Twp.)

2
(Range)

(Meridian)

~~Blanco Navarro~~
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6285 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 9-12-54, 7" casing was found to be parted and collapsed at 2260'.

On 9-14-56, went in hole with Halliburton retainer set at 2125'. Cemented with 100 sacks Ideal regular cement.

Well temporarily abandoned.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bleakwood & Nichols Company (Unit Operator)

Address E. C. Box 1237

Durango, Colorado

By Richard L. Jones DELANEO LOOS

Title Field Superintendent