

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

Sundry Notices and Reports on Wells

93 JUN 15 PM 2:10

1. Type of Well
GAS

5. Lease Number
NM-012710
6. If Indian, All. or
Tribe Name

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

RECEIVED
JUL 22 1998

7. Unit Agreement Name

San Juan 30-6 Unit
Well Name & Number
San Juan 30-6 U #64

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9100

OIL CON. DIV.
DIST. 3

API Well No.
30-039-07896

4. Location of Well, Footage, Sec., T, R, M

990' FNL, 1090' FEL, Sec. 11, T-30-N, R-7-W, NMPM

Field and Pool
Blanco Mesaverde
11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

- | | | |
|---|---|--|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion | <input type="checkbox"/> New Construction |
| <input type="checkbox"/> Final Abandonment | <input type="checkbox"/> Plugging Back | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> Water Shut off |
| | <input type="checkbox"/> Altering Casing | <input type="checkbox"/> Conversion to Injection |
| | <input checked="" type="checkbox"/> Other - Tubing repair | |

13. Describe Proposed or Completed Operations

- 5-11-98 MIRU. SDON.
- 5-12-98 ND WH. NU BOP. TIH, tag fill @ 6328'. TOOH w/201 jts 2 3/8" tbg. Attempt to PT tbg head, failed. TIH w/4 1/2" csg scraper to 6240'. TOOH. SDON.
- 5-13-98 TIH w/RBP, lost in hole. TOOH w/retrieving tool. TIH w/retrieving tool, latch RBP @ 120'. TOOH. SDON.
- 5-14-98 TIH w/4 1/2" CIBP, set @ 5452'. Load csg w/180 bbl 1% KCl wtr. PT csg to 400 psi, failed. TOOH. TIH w/4 1/2" FB pkr, isolate hole in csg @ 2387-2575'. Establish circ down tbg & out hole in csg up annulus w/10 bbl wtr. No blow out bradenhead. TOOH w/pkr, SDON.
- 5-15-98 TIH, ran CBL @ 4000-5454', TOC @ 4640' w/stringers @ 4160' & 4440'. TOOH. (Verbal approval to squeeze 7" csg from Wayne Townsend, BLM). TIH w/csg spear. Latch fish @ 38'. TOOH. TIH, chemical cut csg @ 4057'. TOOH w/fishing tools & 127 jts 4 1/2" csg. SD for weekend.
- 5-18-98 PT 7" csg to 500 psi, failed. TIH w/4 1/2" csg swedge to 4 1/2" lnr top @ 4057'. Work swedge over lnr top. TOOH w/swedge. TIH w/7" FB pkr, set @ 300'. PT 7" csg to 500 psi, failed. TOOH w/pkr. TIH w/watermelon mill. SDON.
- 5-19-98 TIH w/mill. Establish circ. Mill to lnr top @ 4057'. TOOH w/mill. TIH w/7" FB pkr, isolate holes in 7" csg @ 2768-2826'. TOOH w/pkr. SDON.
- 5-20-98 TIH w/pkr, set @ 2826'. PT 7" csg below pkr to 500 psi, OK. Establish injection down csg. ND BOP. Weld on csg stub. PT secondary seal, OK. NU BOP. TIH w/7" pkr, located holes in csg @ 1454' 1486', 1732', 1799', 1861', & 1924'. Attempt to establish injection. SDON.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 6/11/98

ACCEPTED FOR RECORD

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

JUL 20 1998
Date _____

CONDITION OF APPROVAL, if any:

FARMINGTON DISTRICT OFFICE

NMOCD

5-21-98 TOOH w/pkr. TIH, ran csg inspection log @ 0-4057'. Had multiple splits & holes @ 1500-2700'. TOOH. SDON. (Verbal approval to install casing patch from Wayne Townsend, BLM).

5-22-98 TIH w/chemical cutter. Chemical cut csg @ 4069'. TOOH. TIH w/4 1/2" csg spear. TOOH w/4 1/2" csg. TIH to top of csg @ 4069'. Circ hole clean. TOOH. SD for weekend.

5-26-98 TIH w/126 jts 4 1/2" 10.5# K-55 csg patch. Install csg patch @ 4069'. Load csg w/64 bbl wtr. PT csg patch to 200 psi, OK. Pump 30 bbl dyed wtr ahead. Cmtd 4 1/2" csg w/540 sx Class "B" neat cmt w/2% calcium chloride, 2 pps Gilsonite. Displace w/64.5 bbl wtr. No cmt circ to surface. WOC. SDON.

5-27-98 TIH, ran CBL-CCL-GR @ 0-1500', TOC @ 600' w/stringers to 480'. TOOH. (Verbal approval to leave hole as is from Wayne Townsend, BLM). TIH to 3980'. Drill cmt & CO to 5404'. SDON.

5-28-98 Circ hole clean. Drill out CIBP @ 5452'. TIH, circ hole clean. SDON.

5-29-98 TOH. TIH W/193 jts 1 1/2" 2.9# J-55 EUE tbg, landed @ 6200'. ND BOP. NU WH. RD. Rig released.