

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

December 11, 1985

...

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

Mr. Bill Clark
Blackwood & Nichols Co.
P.O. Box 1237
Durango, CO 81302

Dear Bill:

As you are probably aware, there is gas surfacing in Navajo Lake near some of your companies, Northeast Blanco Unit wells.

I am requesting the bradenheads on these wells be tested in the near future. Please dig out the bradenheads and check valves prior to testing. Notify this office at least 24 hours prior to testing, so we may provide a witness. Some of the wells have intermediate casing, be sure both surface pipe and intermediate spools are accessible.

A list of the wells we wish to test follows:

N/E 9-30N-7WNEBU #18 N/E 10-30N-7W NEBU #101 N/W 10-30N-7WNEBU #8-A N/E 03-30N-7W NEBU #16 NEBU #102 s/w 03-30N-7W S/W 02-30N-7W NEBU #15 NEBU #28 S/E 34-31N-7WNEBU #27 N/E 08-30N-7W NEBU #16-A S/E 03-30N-7W NEBU #102-A N/W 03-30N-7W NEBU #17-A N/W 09-30N-7W NEBU #44-A S/E 04-30N-7W

If you have any questions, please contact this office.

Yours truly,

Charles Gholson

Oil & Gas Inspector

CG/dj

xc: Richard Stamets

Operator File Well Files