



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 11, 1985

Mr. Bill Clark
Blackwood & Nichols Co.
P.O. Box 1237
Durango, CO 81302

Dear Bill:

As you are probably aware, there is gas surfacing in Navajo Lake near some of your companies, Northeast Blanco Unit wells.

I am requesting the bradenheads on these wells be tested in the near future. Please dig out the bradenheads and check valves prior to testing. Notify this office at least 24 hours prior to testing, so we may provide a witness. Some of the wells have intermediate casing, be sure both surface pipe and intermediate spools are accessible.

A list of the wells we wish to test follows:

NEBU #18	N/E 9-30N-7W
NEBU #101	N/E 10-30N-7W
NEBU #8-A	N/W 10-30N-7W
NEBU #16	N/E 03-30N-7W
NEBU #102	S/W 03-30N-7W
NEBU #15	S/W 02-30N-7W
NEBU #28	S/E 34-31N-7W
NEBU #27	N/E 08-30N-7W
NEBU #16-A	S/E 03-30N-7W
NEBU #102-A	N/W 03-30N-7W
NEBU #17-A	N/W 09-30N-7W
NEBU #44-A	S/E 04-30N-7W

If you have any questions, please contact this office.

Yours truly,

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Richard Stamets
Operator File
Well Files