

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178 FAX: (505) 334-6170

November 30, 1995

Jack Evans
Schalk Develop Co
PO Box 2078
Farmington, NM 87401

Re: Schalk 55 #1 A-3-30N-05W API 30-039-20586

Dear Jim:

The enclosed copy of the 1995 Bradenhead Test on the referenced well indicates a casing failure. In order to comply with rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity as soon as possible. Please notify the Aztec OCD in time to provide a witness.

Sincerely,



Johnny Robinson
Deputy Oil & Gas Inspector

JR\sh

xc: Well File



STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 11-29-95 Operator Schalk Development Corp.
Lease Name Schalk 55 Well No. 1 Location: Unit A Section 3 Township 30N Range 5W
Pressure (Shut-in or Flowing) Tubing 930 Intermediate N.A. Casing 940 Bradenhead 920

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING	B.H.			
5 min.	<u>N.A.</u>	<u>980</u>	<u>130</u>	Steady Flow	<u>X</u>	<u>N.A.</u>
10 min.	<u>"</u>	<u>540</u>	<u>40</u>	Surges		<u>"</u>
15 min.	<u>"</u>	<u>390</u>	<u>35</u>	Down to Nothing		
20 min.	<u>"</u>	<u>255</u>	<u>35</u>	Nothing		
25 min.	<u>"</u>			Gas	<u>X</u>	
30 min.	<u>"</u>			Gas & Water		
				Water		

If Bradenhead flowed water, check description below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

REMARKS:

This was a retest; B.H. pressures were questionable

By

Steve Atencio

Witness

Conest Cudde P.M.O.C.O.

(Position)