

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-21494
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
LONE STAR INDUSTRIES, INC.	SCHALK - 49
3. ADDRESS OF OPERATOR	9. WELL NO.
C/O JOHN E. SCHALK	2
P.O. BOX 2078 FARMINGTON, NEW MEXICO 87401	10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	PICTURED CLIFFS
850' FROM THE SOUTH LINE, 1765' FROM THE EAST LINE.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SECTION 23, TOWNSHIP 30NORTH RANGE 4 WEST	SEC. 23, T-30N, R-4W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
	7310 GR
	12. COUNTY OR PARISH 13. STATE
	RIO ARRIBA NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other) WELL HISTORY	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-21-73 - 183' KB

RAN 4 JOINTS OF 8-5/8", 32 # CASING TOTALING 168.08' SET AT 183'. CEMENTED WITH 170 SACKS CLASS "A" WITH 2% CALCIUM CHLORIDE AND 1/4# FLOSEAL PER SACK. CEMENT CIRCULATED. PLUG DOWN AT 12:45 A.M. ON 11-22-73.

12- 3-73 - 4500' TD

RAN 143 JOINTS OF 2-7/8", TUBING TOTALING 4474.33' SET AT 4486'. CEMENTED WITH 350 SACKS HALLIBURTON LIGHTWEIGHT AND 100 SACKS OF 50/50 POSMIX. CEMENT CIRCULATED, PLUG DOWN AT 6:45 A.M. ON 12- 3-73.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE DECEMBER 20, 1973

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

