UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE NM 012331 6. IF INDIAN, ALLOTTEE OR TR BE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 30-5 Unit 8. FARM OR LEASE NAME San Juan 30-5 Unit
1. oil gas [X] other  2. NAME OF OPERATOR Northwest Pipeline Corporation	9. WELL NO. 59 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Blanco Pictured Cliffs  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 31 T30N R5W
AT SURFACE: 1100' FNL & 1640' FEL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6830 GR
TEST WATER SHUT-OFF STRACTURE TREAT SHOOT OR ACIDIZE SEPAIR WELL SHOOT OR ALTER CASING SHULTIPLE COMPLETE CHANGE ZONES SABANDON* "Summary of remedial work"	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and
4-28-78 Unseat pkr & moved up hole 5'. l 4-29/5-3-78 Fishing. Unable to recover fish 5-4-78 Released rig 1500 hrs.	Locked up & unable to move. POH.

Subsurface Safety Valve: Manu. and Type	. Set @ Ft.
18. Thereby certify that the foregoing is true and correct  SIGNED TITLE Production Clerk May	26. 1978
SIGNED TITLE TY OUR COUNTY DATE THAT	

(This space for Federal or State office use)

MELY 8 0 1973