F. Carlot

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

5.	LEASE
NM	012709

A511.4 est it Si cytics Obeh

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 30-6 Unit
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other	San Juan 30-6 Unit
2. NAME OF OPERATOR	7A 26 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
EL PASO NATURAL GAS CO.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
BOX 990, FARMINGTON, NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 30, T-30-N,R-7-W
below.) AT SURFACE: 1730'N,790'W	NMPM
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6206' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF  FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
CHANGE ZONES	
ABANDON*	
(other)	그는 그는 한 그 문화생활이 되는 회학학생은 불다.
measured and true vertical depths for all markers and zones pertinent 7/5/78: Spudded well. Drilled surface how H-40 surface casing 213' set at 226'. Cem Circualted to surface. WOC 12 hours; held	ele. Ran 5 joints 9 5/8", 32.3# Hented with 224 cu. ft. cement.
Subsurface Safety Valve: Manu. and Type	Set @Ft.
18. Thereby certify that the foregoing is true and correct	
SIGNED JAPES DRANGUELA TITLE Drilling Cler	k DATE 7/6/78
(This space for Federal or State off	ice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	REGEIV

\*See Instructions on Reverse Side

JUL 1 0 1978

U. S. GEOLOGICAL SURVEY DURANGO, COLO.