5. LEASE

SF 078997

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservair. Use Form 9-331-C for such proposals.)	San Juan 30-5 Unit
eservoir. Use Form 9 -331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil 225 (57)	San Juan 30-5 Unit
1. oil ges (XI other	9. WELL NO.
2. NAME OF OPERATOR	49
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Box 90 Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA
helow)	Sec. 9, T30N, R5W
AT SURFACE: 1005' FWL & 815' FSL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6318' GR
TEST WATER SHUT-OFF LI LI FRACTURE TREAT []	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES L. L. L. L. ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demonstred and true vertical depths for all markers and zones pertined. Northwest Pipeline Corporation will drill. Therefore, please rescind the Sundry Notice. Location was built in 1975 and has not been	this well. c dated November 22, 1977.
	i Jun 3 18/8
	NOIL CON. COM.
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. Thereby certify that the foregoing is true and correct	
SIGNED TITLE Drilling Eng	incer DATE May 31, 1978
(This space for Federal or State of	ffice use)
APPROVED BY TITLE TITLE	DATE