8-19-79

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 30-6 Unit 8. FARM OR LEASE NAME
1. oil gas X other	San Juan 30-6 Unit
well well other 2. NAME OF OPERATOR	9. WELL NO. 66A
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1460'N, 1470'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-30-N, R-7-W N.M. P.M. 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6277' G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner TD 3411'. Ran 84 joints 7", 20#, K-55 interm 	irectionally drilled, give subsurface locations and at to this work.)*
cemented w/303 cu. ft. cement. WOC 12 hours; cement 1900'.	held 1200#/30 minutes. Top of
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
	erk DATE August 21, 1979
(This space for Federal or State off	ice use)
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	DATE -

AUG 2 9 1979