8-23-79

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES

18. I hereby certify that the foregoing is true and correct

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 0807116. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 30-6 Unit 8. FARM OR LEASE NAME
1. oil gas x other	San Juan 30-6 Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	26 A 10. FIELD OR WILDCAT NAME Blanco MV
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1470'N, 1845'W	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T-30-N, R-6-W N.M.P.M.
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent PBTD 6194'. Tested casing to 3500#, OK. Perfet 5812,5818,5824,5830,5836,5871,5879,5887,5900,56120,6132,6190' W/1 SPZ. Fraced w/77,500# 20/4 Flushed w/8,526 gal. water. Perfed C.H. & Men 5424,5439,5447,5455,5476,5505600,5606,5679'W/1 SPZ. Fraced w/60,060# 20/40w/7,728 gal. water. 	rectionally drilled, give subsurface locations and to this work.)* ed P.L. 5768,5775,5782,5800,5806,6918,5971,5990,6009,6016,6068,60 sand, 155,000 gal. water.
Subsurface Safety Valve: Manu. and Type	Set @Ft.

AUG 2 9 1979

(This space for Federal or State office use)

TITLE __Drilling _Clerk date __August 24, 1979

___ DATE _