UNITED STATES DEPARTMENT OF THE INTERIOR

	- Bua	get Bureau	NO. 42	R142
FACE				
LEASE				

DEPARTMENT OF THE INTERIOR	M 03385	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 30-6 Unit 8. FARM OR LEASE NAME	
1. oil gas well well other	San Juan 30-6 Unit	
2. NAME OF OPERATOR EL PASO NATURAL GAS COMPANY	9. WELL NO. 18 A	
3. ADDRESS OF OPERATOR	Blanco MV	
BOX 289, FARMINGTON, NEW MEXICU 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1800'S, 910'E	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-30-N, R-6-W N.M.P.M. 12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6424' G.L.	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	
CHANGE ZONES		
at 3/02'. Cemented w/286 cu. ft. cemer	irectionally drilled, give subsurface locations and to this work.)*	
minutes. Top of cement 2400'. -25-79: TD 6030'. Ran 76 jts. 4 1/2", 10.5#, k 3548-6030'. Float collar set at 6014'. WOC 18 hours.	<pre><-55 casing liner, 2482' set at Cemented w/438 cu. ft. cement.</pre>	
Subsurface Safety Valve: Manu. and Type	Set @ Ft:	
18. I hereby certify that the foregoing is true and correct SIGNED AMAY XAMAULA TITLE Drilling Cle	erk DATE July 25, 1979	
(This space for Federal or State offi	ce use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE	

그런데 되워 될

See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY