

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR  
Northwest Pipeline Corporation
3. ADDRESS OF OPERATOR  
P.O. Box 90, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1120' FSL & 1580' FEL  
AT TOP PROD. INTERVAL: Same as above  
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Drlg operations ☒

SUBSEQUENT REPORT OF:

- ☐  
☐  
☐  
☐  
☐  
☐  
☒

5. LEASE  
NM 012335
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
San Juan 30-5 Unit
8. FARM OR LEASE NAME  
San Juan 30-5 Unit
9. WELL NO.  
#14A
10. FIELD OR WILDCAT NAME  
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 31, T30N, R5W
12. COUNTY OR PARISH  
Rio Arriba
13. STATE  
New Mexico
14. API NO.  
30-039-22192
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6672' GR

(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

RECEIVED  
APR 21 1981  
OIL CON. COM.  
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-1-81 Drlg w/ gas at a depth of 4606'.

4-2-81 Drlg w/ gas at a depth of 5870' and drlg ahead to a depth of 6031' (TD)

4-3-81 Gearhart ran IEL/ GR/CDL/SNL logs. Ran 72 jts (2249') of 4-1/2", 10.5# K-55, ST&C & set at 6031'. FC at 5998' & top liner at 3782' KB. Halliburton cmt'ed w/ 220 sx Cl "B" w/ 4% gel & 12-1/2# fine gilsonite/sx. Displaced plug w/ 60 bbls wtr. Left 222' of cmt in 4-1/2" liner. Plug down at 0230 hrs 4-3-81. Reversed out 10 bbls gel wtr, 0 bbls cmt. Job completed at 0315 hrs 4-3-81. Released rig at 0600 hrs 4-3-81.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE April 6, 1981  
Donna J. Brace

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 21 1981  
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

FARMINGTON DISTRICT

BY DM

\*See Instructions on Reverse Side

djb/