

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR  
Northwest Pipeline Corporation

3. ADDRESS OF OPERATOR  
P.O. Box 90, Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 800' FSL & 1785' FWL  
AT TOP PROD. INTERVAL: Same as above  
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) Drilg operations

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

5. LEASE  
SF 078994

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
San Juan 30-5 Unit

8. FARM OR LEASE NAME  
San Juan 30-5 Unit

9. WELL NO.  
#52

10. FIELD OR WILDCAT NAME  
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 15 T30N R5W

12. COUNTY OR PARISH | 13. STATE  
Rio Arriba | New Mexico

14. API NO.  
30-039-22574

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6584' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2-14-81 GO ran IES & SNP/CDL/GR Logs. Loggers TD @ 8037'. Ran 201 jts (8019') of 4-1/2" (1321' of 11.6# & 7798' of 10.5#) K-55, ST&C & set at 8033' Top of FC @ 8021'. National cemented w/ 260 sx C1 "B" w/ 8% gel, 12-1/2# fine gils/sx & 0.4% HR-4. Tailed w/ 100 sx C1 "B" w/ 1/4# fine tuf-plug sx & 0.4% HR-4. Plug displaced w/ 127 bbls wtr & down @ 2115 hrs. Wilson ran temp survey & found cmt top @ 2900' w/ PBTD @ 7999'.

NOW WAITING ON COMPLETION

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE 2-26-81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONFIDENTIAL

NMOCC

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

MAR 4 1981

FARMINGTON DISTRICT  
BY SEM