REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING

REPAIR WELL

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

6-15-81 Drlg ahead to a depth of 5700'.

Dec. 1973	
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 079000-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME San Juan 31-6 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a differenceservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME San Juan 31-6 Unit
1. oil gas well other 2. NAME OF OPERATOR	9. WELL NO. #7A
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME Blanco Mesa Verde
 ADDRESS OF OPERATOR P.O. Box 90, Farmington, N.M. 87401 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA
below.) AT SURFACE: 990' FSL & 1830' FEL AT TOP PROD. INTERVAL: Same as above	Sec 1, G30N, R7W 12. COUNTY OR PARISH 13. STATE Rio Arriba N.M.
AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD 6329' GR
SUBSECUENT REPORT OF	and the state of t

(MOTE: Report results of multiple complete

cliange on Forn

CALOGROAL SURVEY MULTIPLE COMPLETE CHANGE ZONES epid andrem. ABANDON* pud, surface, intermediate 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is direct onally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF

6-16-81 Gearhart ran Induction & Neutron Density/GR logs. Ran 75 jgs (2303') of 4-1/2", 10.5#, K-55, ST&C & set liner from 3393' to 5696' KB. National Cmt'ed w/ 230 sx Cl "B" containing 4% gel & 12-1/2# fine gils/sx. Displaced plug w/ 60 bbls wtr & down @ 1500 hrs 6-16-81. Reversed out 12 bbls cmt. Released rig # 1900 hrs.

NOW WAITING ON COMPLETION.

Subsurface Safety Valva: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Production Clerk DAT Donna J Brace (This sees for Federal or State office Use)	E 6-24-81
(This space for redefal of state office of the	
APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:	ATE ACCEPTED FOR RECORD