

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-039-22756
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Disposal ☐

2. Name of Operator
Mallon Oil Company

3. Address of Operator
P.O. Box 3256

4. Well Location
Unit Letter J : 1730 Feet From The South Line and 1820 Feet From The East Line

Section 13 Township 30N Range 4W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
7023 GL

7. Lease Name or Unit Agreement Name
Simms Federal

8. Well No.
1

9. Pool name or Wildcat
East Blanco Entrada

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As per verbal approval recieved 2-13-98 from Frank Chavez, Mallon Oil revised the casing program as per the attached wellbore diagram.

RECEIVED
FEB 20 1998
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Gay Davis TITLE Production Analyst DATE 2/17/98
TYPE OR PRINT NAME M. Gay Davis TELEPHONE NO 505-885-4596

(This space for State Use)

APPROVED BY Johnny Robinson TITLE DEPUTY OIL & GAS INSPECTOR DATE FEB 20 1998
CONDITIONS OF APPROVAL, IF ANY:

MALLON OIL COMPANY

ENGINEERING CHART


FILE _____

APPN _____

DATE _____

BY _____

SUBJECT Simms #1
Unit 5 Sec 13-T30N R4W



Any remedial work inside liner done through 3 1/2\" Tools

Cement Program: 10 bbls Sodium Silicate pre flush
 Band enhancement,
 (Rotate liner 65 sks 50/50 Poz class H
 while cementing) .8 FL52, 2% gel, 2% RB
 35% silica flour
 24 hr comp. 2174 psi