

District I

P.O. Box 1960, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources DepartmentSUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

DEPUTY OIL & GAS INSPECTOR

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP 15 1995

PIT REMEDIATION AND CLOSURE REPORTOperator: Phillips Petroleum Company Telephone: (505) 599-3400Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401Facility Or: San Juan 31-6 Unit #48Well Name PLocation: Unit or Qtr/Qtr Sec SE SE Sec 2 T 30N R 6W County Rio ArribaPit Type: Separator X Dehydrator Other Land Type: BLM State X Fee Other Pit Location: Pit dimensions: Length 30' width 30' depth 3-1/2'
(Attach diagram)Reference: wellhead X other Footage from reference: 45Direction from reference: 60 Degrees X East North X
of
West South

Depth to Ground Water: <u>200</u> (vertical distance from contaminants to seasonal highwater elevation of ground water)	<u> </u>	Less than 50 feet	(20 points)	
	<u> </u>	50 ft to 99 feet	(10 points)	
	<u>X</u>	Greater than 100 feet	(0 points)	<u>0</u>

Wellhead Protection Area: (less than 200 feet from a private domestic water source, or: less than 1000 feet from all other water sources).	<u> </u>	Yes	(20 points)	
	<u>X</u>	No	(0 points)	<u>0</u>

Distance to Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches.)	<u> </u>	Less than 200 feet	(20 points)	
	<u> </u>	200 feet to 1000 feet	(10 points)	
	<u>X</u>	Greater than 1000 feet	(0 points)	<u>0</u>

PITCFRM.WK3

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: N/A Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: N/A

Initial assessment showed soils to be clean at the surface and at
three feet below pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths) Sample depth 3' below pit bottom

Sample date 9-7-93 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 23

TPH 0

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST
OF MY KNOWLEDGE AND BELIEF.

DATE 8/19/94 PRINTED NAME Ed Hasely

SIGNATURE Ed Hasely and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT SUMMARY

1993

ENVIROTECH, INC.

REVISED DATE: SEPTEMBER 09, 1993

REC

REVISED DATE: SEPTEMBER 09, 1993																			REC'D	
PIT NO.	WELL NAME	U-S-T-R	PIT TYPE	RANK SCORE	CLOSURE STANDARD TYPH (PPM)	DATE 1993	GROUNDWATER ENCOUNTERED Sub-Surf Depth	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Meter (PPM)	Total Recoverable Pet. Hydro. (PPM)		EPA METHOD 8020 (PPB)				TOTAL BTEX	STATUS	
												Benzene	Toluene	Ethyl Benzene	Xylene					
PA056	SAN JUAN 29-6, #9	M362906	SEP	10	1000	9-03	NO	CL	EARTHEN	T1-4.5	0	0	0						CLOSE	
										T1-7	0	0	0							
PA057	SAN JUAN 29-6, #25	B322906	SEP	10	1000	9-03	NO	SM	EARTHEN	T1-4	718	100	15.3						CLOSE	
										T1-6.5	851	100		97		23.3	272	407.6		
PA058	SAN JUAN 29-6, #55A	C182906	SEP	20	100	9-03	NO	SM	EARTHEN	T1-6	665	1800							REM	
										T1-11	555	2000								
										T1-14	512	3300								
										T2-5	0									
										T2-10	43	10								
										T2-15	629	1800								
PA059	SAN JUAN 30-5, #95 DK	H283005	SEP	10	1000	9-07	NO	CL	EARTHEN	T1-4.5	195	0							REM?	
										T1-7	87	0								
PA060	SAN JUAN 31-6, #37 DK	P363106	SEP	0	5000	9-07	NO	SM	EARTHEN	T1-4	50	4400							CLOSE	
PA061	SAN JUAN 31-6, #42 DK	A363106	SEP	0	5000	9-07	NO	SP	EARTHEN	T1-2.5	171	760							CLOSE	
PA062	SAN JUAN 31-6, #38 DK	C023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-5.5	16	34							CLOSE	
										T1-8	24									
PA063	SAN JUAN 31-6, #48 DK	P023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-4	23	0							CLOSE	
										T1-6.5	23	0								
PA064	SAN JUAN 31-6, #46	A323106	SEP	20	100	9-08	NO	CL	EARTHEN	T1-6.5	10	0							CLOSE	
										T1-9	0	0								
PA065	SAN JUAN 31-6, #47 DK	L323106	SEP	0	5000	9-08	NO	CL	EARTHEN	T1-5	20	12							CLOSE	
										T1-7.5	53									
PA066	SAN JUAN 29-6, #15-2	K022906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5	5	110	42.9				7570	8520.9	CLOSE	
										T1-7	905									
PA067	SAN JUAN 29-6, #37-16	A162906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5	707	44	16.4				498	1249	REM?	
										T1-7	817			710		24.6				

SOIL TYPE: C - Clay, M - Silt, S - Sand, G - Gravel Plasticity: L - Low, H - Plastic Grading: P - Poor, A - Average