Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

	Duager	 		• • •
		 	_	_
FACE				

DEPARTMENT OF THE INTERIOR	NM - 28717			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME			
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME			
1 -11	Bixler Ranch			
1. oil gas W other	9. WELL NO.			
2. NAME OF OPERATOR	#2			
	10. FIELD OR WILDCAT NAME			
Southland Royalty Company	Blanco Pictured Cliffs			
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR			
P.O. Drawer 570, Farmington, NM 87499	AREA			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Section 26, T30N, R4W			
below.)				
AT SURFACE: 1050' FSL & 800' FWL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL:	Rio Arriba NM			
AT TOTAL DEPTH:	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA	5. ELEVATIONS (SHOW DF, KDB, AND WD)			
	7442' GL			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7772			
TEST WATER SHUT-OFF	S. J.			
FRACTURE TREAT	· · · · · · · · · · · · · · · · · · ·			
SHOOT OR ACIDIZE	THE BELLE			
REPAIR WELL \[\sum_{\infty} \cdot \cdot \sum_{\infty} \sum_{\infty} \cdot \sum_{\infty} \cdot \sum_{\infty} \cdot \sum_{\infty} \cdot \sum_{\infty} \sum_{\infty} \cdot \sum_{\infty} \sum_{\inft	(NOSE: Report results of multiple completion or zone			
PULL OR ALTER CASING L	が、schange or Form 9–330.)			
MULTIPLE COMPLETE	AUG 2 2 1983			
CHANGE ZONES	Carrie Marie Carrier			
ABANDON* (other) Spud & Casing Report X	$oldsymbol{arphi}_{A}$			
	Dist. 3			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	illectionally diffied. Sive audautiace locations and			
8-8-83 Spudded 12-1/4" surface hole at 12:45 total depth of 220'. Set 5 joints (20 212'. Cemented with 165 cubic feet of flocele and 3% CACL2. Plug down at 6 circulated to surface.	00') of 8-5/8", 24# casing at f Class "B" cement with 1/4#			
8-9-83 Pressure tested casing to 600 psi.				
Subsurface Safety Valve: Manu. and Type	Set @ F			
18. I hereby certify that the foregoing is true and correct				
SIGNED Sherry Merley TITLE Secretary	DATE August II, 1983			
(This space for Federal or State o	mee use)			
APPROVED BY TITLE	DAACCEPTED FOR RECORD			
CONDITIONS OF APPROVAL, IF ANY:				

AUG 1 9 1983

*See Instructions on Reverse Side