

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other2. NAME OF OPERATOR
Phillips Petroleum Company3. ADDRESS OF OPERATOR
P. O. Box 2920, Casper, Wyo. 826024. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1120' FNL, 870' FEL (NE NE)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Shut-in ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-5-84 - Ran liner to 14,026' KB. Hung off at 7756' KB. Tested liner to 4000 psi. Held ok. Ran 3 1/2" 19.95# RY85 pH-6 Hydril tubing. Tag PBTD at 13,960' KB. Landed tubing at 13,732'. Displaced hole with 10.0 ppg brine water. Nipple up 10m tubing bonnet with 10m 4" FE gate valve. Well shut-in awaiting completion.

See attachment.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. W. Berk TITLE RMR Drilling Mgr. DATE 4-4-85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

- 0+3 - BLM, Farmington, NM
2 - NM Oil Cons. Comm.
1 - A. E. Stuart - Casper
1 - Well File