

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

SLOPE TEST

Hole Deviation

147 ft.	$3/4^\circ$
660 ft.	$1-3/4^\circ$
911 ft.	4°
941 ft.	$4-1/4^\circ$
1064 ft.	$4-1/4^\circ$
1215 ft.	$4-1/4^\circ$
1240 ft.	4°
1309 ft.	4°
1370 ft.	3°
1742 ft.	2°
1835 ft.	$2-1/2^\circ$
1927 ft.	$2-3/4^\circ$
1988 ft.	$2-1/2^\circ$

RECEIVED
DEC 12 1986
OIL CON. DIV.
DIST. 3

State of New Mexico)
) ss
County of San Juan)

I, Kevin H. McCord, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 11th day of December, 1986.

Notary Public

My Commission Expires

09-20-88

Slope Test, Cont.
Jicarilla 458 #2

2357 ft.	2-1/2°
2449 ft.	2-1/4°
2542 ft.	2-3/4°
2635 ft.	3°
2729 ft.	2-1/2°
2851 ft.	3°
2944 ft.	3°
3035 ft.	2-3/4°
3129 ft.	2-3/4°
3250 ft.	2-3/4°
3372 ft.	3°
3525 ft.	3°
3679 ft.	1-1/2°
3802 ft.	1-1/2°
3960 ft.	1-1/2°