

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u> <u>(Degrees)</u>
148'	1/2
649'	1 3/4
830'	1
1365'	1/4
1844'	1 1/4
2273'	1
2768'	1 3/4
2992'	2
3260'	4 3/4
3351'	4 1/2
3443'	4 1/2
3544'	4
3637'	4 1/2
3669'	4 1/2
3819'	2 3/4
4112'	1 1/4
4150'	1

State of New Mexico)
) ss
County of San Juan)

I, Kevin H. McCord, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Kevin H. McGold

Kevin H. McCord
Engineer

Subscribed and sworn before me ~~this~~ 23rd day of November,
1987.

Eileen Hare

Notary Public

My Commission Expires:

9-20-88