

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

OCT 31 1988

OIL CON. DIV.
DIST. 3

SLOPE TEST

HOLE DEVIATION
(Degrees)

137		1/2
386		3/4
663		1
912		1 1/2
1171		1 3/4
1660		1/4
1909		1/2
2166		1/4
2653		3/4
3125		1/2
3601		1/2
4075		1/2

I, Kevin H. McCord, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Kevin H. McGold

Gayle Fielder
Notary Public

08-23-90

