

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill, deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: oil well _____ gas well _____ other Pressure Observation

2. Name of Operator: Blackwood & Nichols Co., A Limited Partnership

3. Address of Operator: P.O. Box 1237, Durango, CO 81302-1237

4. Location of Well: (Footage, Sec., T., R., M., or Survey Description)

160' FNL, 1555' FEL - Section 17, T30N, R7W

5. Lease Designation & Serial #:

SF-079060

6. If Indian, Allottee/Tribe Name

7. If Unit or CA, Agmt. Design.:

Northeast Blanco Unit

8. Well Name and No.:

N.E.B.U.# 429

9. API Well No.:

30-039-24356

10. Field & Pool/Expltry Area:

Basin Fruitland Coal

11. County or Parish, State:

Rio Arriba, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION |
|---|---|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Plugging Back |
| | <input type="checkbox"/> Casing Repair |
| | <input type="checkbox"/> Altering Casing |
| | <input checked="" type="checkbox"/> Other: Bottom Hole Pressure Measurement |
| | (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) |
| | <input type="checkbox"/> Change of Plans |
| | <input type="checkbox"/> New Construction |
| | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Water Shut-Off |
| | <input type="checkbox"/> Conversion to Injection |

13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

A Bottom Hole Pressure Measurement was taken April 7, 1993 for the NEBU 429.

Pressure - 697 psig
Depth - 3094 feet

RECEIVED

JUN 3 1993

OIL CON. DIV.

DIST. 3

070 FARMINGTON, NM

93 MAY 27 AM 11:29

RECEIVED
BLM

14. I hereby certify that the foregoing is true and correct.

Signed: AL RECTOR AL RECTOR

Title: DISTRICT SUPERINTENDENT

Date: 5/24/93

(This space for Federal or State office use)

Approved By _____ Title _____
Conditions of approval, if any:

ACCEPTED FOR RECORD

MAY 28 1993

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department, office or the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

BY