## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	ices and Reports on Wells	· 		
	STOES and Reports on Wells	FN 1: 29	5.	Lease Number
I. <b>Type of Well</b> GAS	60 Thin	GION, NA	6.	SF-079382 If Indian, All. or Tribe Name
2. Name of Operator			7.	Unit Agreement Name
RESOURCES OIL	& GAS COMPANY			San Juan 30-6 Unit
Address & Phone No. of Opera	<b>*</b>		8.	
PO Box 4289, Farmington, NM			9.	San Juan 30-6 U #413 API Well No. 30-039-24396
4. Location of Well, Footage, Sec., T, R, M			10.	Field and Pool
1370'FSL, 1330'FWL, Sec.23,	T-30-N, R-7-W, NMPM		11.	Basin Fruitland Coal County and State Rio Arriba Co, NM
Final Abandonment	Casing Repair Altering Casing X Other - Recavitate			
3. Describe Proposed or Comp	leted Operations			-
It is intended to recavit	ate the subject well in t	he follow	ving	manner:
stabilizes. Clean casing liner. The	ng natural and air assiste the well to total depth a liner will be pre-perfora s. Rerun the production to	ed surges and run a ated with	unti 5 1/ -4 sh	il the well /2" 15.5# K-55 nots per foot across
		0		GEIVED AN 1 5 1998
4. I hereby certify that the	foregoing is true and co			CON. DIV.
signed Status Status	(DWSFTC) Title Regulato		.stra	
This space for TS/Duane W. Special Property of the Condition of Approval, if any:	Coffice use) Title	Dat	:e _	JAN 1 2 1998