

DEPARTMENT OF THE INTERIOR (Reverse Side)  
BUREAU OF LAND MANAGEMENT

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

|   |  |  |                   |
|---|--|--|-------------------|
| 1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER  |  | 5. LEASE DESIGNATION AND SERIAL NO.<br>SF-078994                       |                   |
| 2. NAME OF OPERATOR<br>Phillips Petroleum Company   |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                   |                   |
| 3. ADDRESS OF OPERATOR<br>300 W. Arrington, Suite 200, Farmington, N.M. 87401   |  | 7. UNIT AGREEMENT NAME<br>San Juan 30-5 Unit                           |                   |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)<br>At surface<br>Unit L 2090' FSL & 1197' FWL |  | 8. FARM OR LEASE NAME  |                   |
| 14. PERMIT NO.<br>30-039-24790  |  | 9. WELL NO.<br>207   |                   |
| 15. ELEVATIONS (Show whether DF, RT, CR, etc.)<br>6329'   |  | 10. FIELD AND POOL, OR WILDCAT<br>Basin Fruitland Coal                 |                   |
|   |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 18, T30N, R5W |                   |
|   |  | 12. COUNTY OR PARISH<br>Rio Arriba                                     | 13. STATE<br>N.M. |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                      |   | SUBSEQUENT REPORT OF:                          |  |
|--|---|--|--|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> | WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>  |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETION <input type="checkbox"/>  | FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input type="checkbox"/>             | SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/>    |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANE <input type="checkbox"/>         | (Other) <input type="checkbox"/>               |  |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 7-31-90 - MIRU Aztec Well Service Rig No. 301. Spudded 12 1/4" hole at 3:15 P.M. Ran 9 5/8", 36#, K-55, ST&C casing set at 282'. RU Howco cement with 250 sx cl 'B' cement with 3% CaCl<sub>2</sub> and 1/4# flocele/sk. Circ. 90 sx cement. Plug down at 12:45 A.M. Bumped plug w/500 psi Float held. WOC 6 hrs. NU BOP.
- 8-03-90 - RU casing crew. Ran 7", 23#, J-55, LT&C casing set at 2990'. RU Howco & cement w/500 sx 65.35 POZ w/12% gel & 1/4# flocele/sk followed by 100 sx cl 'B' with 1/4# flocele/sk followed by 50 sx cl 'B' cement w/0.75% CFR-3. Circ. 170 sx cement. Plug down at 10:00 A.M. Bumped plug with 1500 psi. Float held. PU BOP and set slips with 60,000#. RD & released rig.

RECEIVED  
SEP 04 1990  
OIL CON. DIV  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. Kieke, Jr. TITLE Area Landman DATE 8-13-90  
505-599-3410  
(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 27 1990  
CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

BY MT