UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| Sundry Notices and Reports on Wel | ls |
|---|---|
| 1. Type of Well GAS | 5. Lease Number SF-079382 6. If Indian, All. or Tribe Name |
| 2. Name of Operator Meridian Oil Inc. | 7. Unit Agreement Name San Juan 30-6 Unit |
| 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1065'FNL, 1680'FEL Sec.23, T-30-N, R-7-W, NMPM | 8. Well Name & Number San Juan 30-6 U #404R 9. API Well No. 30-039-25241 10. Field and Pool Basin Ft Coal 11. County and State Rio Arriba Co, NM |
| Subsequent Report Plugging Back Casing Repair | |
| 13. Describe Proposed or Completed Operations | |
| 02-13-93 TD 3033'. Ran 6 jts 5 1/2", 23.0#, P-11 liner, 252' set @ 3033'. Top of liner home. | |
| MAR 3 1993 OIL CON. DIV | RECEIVED BLM 93 FEB 22 PH 2: 22 070 FASSLACTON, NM |
| 14. I hereby certify that the foregoing is true and o | correct. |
| Signed Signed Malkeel Title Regulatory Af | <u>fairs</u> Date 2/15/93 |
| (This space for Federal or State Office use) APPROVED BYTitle | ACCEPTED FUE RECORD |
| CONDITION OF APPROVAL, if any: | EEB Signal |

TARIMINOTOR HEROU FOR AREA