

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-039-25265 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name San Juan 30-5 Unit |
| 8. Well No. 246 |
| 9. Pool name or Wildcat Basin Fruitland Coal |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6545' (GL Unprepared) |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | 2. Name of Operator Phillips Petroleum Company |
| 3. Address of Operator 5525 Hwy. 64, NBU 3004, Farmington, New Mexico 87401 | 4. Well Location Unit Letter L : 2011 Feet From The South Line and 531' Feet From The West Line Section 26 Township 30N Range 5W NMPM Rio Arriba County |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: 7" Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-31-93

RU & RIH w/7" 23#, J-55 ST&C casing and set at 3150' at 2045 hrs. on 8-31-93. RU Western and cemented with 500 sx 65/36 POZ w/12% Gel & 1/4# celloflake & 150 sx C1 "B" cement w/2% CaCl₂ & 1/4# sk celloflake -disp w/fr wtr. Bumped plug @ 2215 hrs had 82 bbls cement returns to pit. ND BOPs, set slips, NU wellhead. RD MO rig.

(Waiting on completion rig).

RECEIVED
SEP - 3 1993
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ed Hasely Ed Hasely TITLE Environmental Engineer DATE 9-3-93
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Original Signed by FRANK I. CHAVEZ TITLE SUPERVISOR DISTRICT I DATE SEP - 8 1993
CONDITIONS OF APPROVAL, IF ANY: