

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-039-25265
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name San Juan 30-5 Unit
8. Well No. 246
9. Pool name or Wildcat Basin Fruitland Coal
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6559' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Phillips Petroleum Company
3. Address of Operator 5525 Hwy. 64, NBU 3004, Farmington, NM 87401 (505) 599-3454

4. Well Location Unit Letter L : 2011' Feet From The South Line and 531' Feet From The West Line Section 26 Township 30N Range 5W NMPM Rio Arriba County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6559' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: 4 1/2" liner not run <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
--

The San Juan 30-5 Unit # 246 would not cavitate during the initial completion. The 4 1/2" liner was not run due to anticipated future wellbore cleanout to sustain gas production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>Ed Hasely</u>	TITLE <u>Environmental Engineer</u>	DATE <u>9-24-93</u>
TYPE OR PRINT NAME <u>Ed Hasely</u>	<u>(505) 599-3460</u>	TELEPHONE NO.

(This space for State Use)		
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPPLEMENTAL DISTRICT</u>	DATE <u>SEP 24 1993</u>
CONDITIONS OF APPROVAL, IF ANY:		