



Key Energy Services, Inc.

Four Corners Division
5651 US Highway 64
P.O. Box 900
Farmington, NM 87499


Phone: 505-327-4935
Fax: 505-327-4962

January 17, 2001

Rig No. 53

Phillips Petroleum Company
5525 Hwy 64 NBU 3004
Farmington, NM 87401

Attn: Patsy Clugston



This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 30-5 #214 well in S05-T30N-R05W, in San Juan, county, New Mexico.

Depth	Deviation	Depth	Deviation
219'	$\frac{1}{2}^{\circ}$	2190'	$\frac{3}{4}^{\circ}$
700'	$\frac{3}{4}^{\circ}$	2679'	1°
1194'	$\frac{3}{4}^{\circ}$	3052'	$\frac{1}{2}^{\circ}$
1685'	$\frac{1}{4}^{\circ}$		

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager

Notary Public

My commission expires:

6/26/02