

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office 60143 78  
Lease No. 10701  
Unit 1st

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 7 is located 100 ft. from N line and 100 ft. from E line of sec. 11  
1 (1/4 Sec. and Sec. No.) 100 (Twp.) 100 (Range) 100 (Meridian)  
100 (Field) 100 (County or Subdivision) 100 (State or Territory)

The elevation of the derrick floor above sea level is 1772 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled 1/11/51. at 125' of 3 1/2" surface casing at 100' down  
 100' make a cement. Cased casing for 30' casing with 100' produce  
 no water. Cased casing 1/15/51. Cased for 30' casing with 100'  
 produce - drop in production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 100143 78

Address 100

100143 78

By ORIGINAL SIGNED BY ICE C. SALMO

Title 100143 78