



TONEY ANAYA  
GOVERNOR

STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

May 22, 1986

Dugan Production Corp.  
P.O. Box 208  
Farmington, NM 87499

Re: Central Cha Cha Unit #4, K-31-29N-13W

Gentlemen:

The annual mechanical integrity test on the referenced water injection well indicated a casing or packer leak. In order to insure the protection of hydrocarbon and fresh water zones, you are hereby directed to initiate remedial action within 60 days. A copy of the test is enclosed for your reference.

Yours truly,

A handwritten signature in cursive script, reading "Carolyn J. Taplin".

Carolyn J. Taplin  
Field Representative

CJT/dj  
Enclosure

xc: Prentiss Childs  
UIC File  
Operator File  
Well File