

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lesse No. 080247
Unit _____

RECEIVED

SEP 21 1949
U. S. GEOLOGICAL SURVEY
SANTA FE, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	X	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECKING MARKS IN LINE OF REPORT, NOTICE, OR OTHER DATA)

September 13, 1949

1 Bradley Federal
Well No. _____ is located 1650 ft. from N line and 990 ft. from E line of sec. 35
QW 2 204 104 204 104 104
(Q. Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Willamette San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. will be supplied

DETAILS OF WORK

(State names of and expected depths to objective sands, shales, limestones, and depths of proposed casings; indicate modifying jobs, cementing, etc. (omit all other incidental proposed work))

Well has been drilled to a T. B. of 1100'. Heavy artesian H₂O flow encountered 350-500. It is planned to set casing in this well and complete as a water well for use in future drilling. H₂O 7" used seamless tubing cemented with 200 grout will be used.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Llano Gas Company

Address 1315 Pacific Ave.

El Paso, Texas

By Frank A. Schmitt
Title Vice President