

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358 4.
Approval expires 12-31-61

Land Office Santa Fe
Lease No. SM 04570
Unit Mexico-Ped #2

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	Surface	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....		
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....		
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 2, 1959

Mexico-Ped #2


Well No. 1 is located 1190 ft. from N line and 1170 ft. from E line of sec. 32
NE/4 - Section 32 27N 10W TXPK
1/4 Sec. 32 27N 10W TXPK
1/4 Sec. 32 27N 10W TXPK
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5615 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 4:00 P.M. December 2, 1959. Drilled 8-3/4" hole to 162'. Ran 8-3/4" hole to 13-3/4" to 199'. Ran and set 10-3/4" CG casing at 154' and cemented with 175 sacks of regular cement, 2000 lbs. Cement circulated to surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY
Box 436
 Address Farrington, New Mexico

By (Signed) P. E. Cosper
District Superintendent
 Title

