

District III
P.O. Box 10000
Farmington, NM 88401
DEPUTY OIL & GAS INSPECTOR
P.O. Box 10000
Farmington, NM 88401

State of New Mexico
Energy, Minerals and Natural Resources Department

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

OIL CONSERVATION DIVISION

2040 South Pacheco Street
Santa Fe, New Mexico 87505

District III
1000 Rio Brazos Rd. Santa Fe, NM 87505
FEB 28 1997

PIT REMEDIATION AND CLOSURE REPORT

RECEIVED
OCT 31 1996

OIL CON. DIV.

PAGE 3

Operator: PNM Gas Services (Meridian) Telephone: 324-3764
Address: 603 W. Elm Street Farmington, NM 87401
Facility or Well Name: Congress #4
Location: Unit: 990 FSL/790 FEL Sec. 35 T. 29 N R. 11 W County San Juan
Pit Type: Separator Dehydrator Other Abandoned
Land Type: BLM ☒ State ☐ Fee ☐ Other ☐

Pit Location: Pit dimensions: length 15 width 15 depth 3
(Attach diagram) Reference: wellhead ☒ other ☐
Footage from reference: 120'
Direction from reference: 90 Degrees ☒ East North ☒
West South

Depth to Ground Water:

(Vertical distance from contaminants to
seasonal high water elevation of ground
water)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or, less than 1,000
feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance to Surface Water:

(Horizontal distance to perennial lakes,
ponds, rivers, streams, creeks, irrigation
canals and ditches)

Less than 200 feet (20 points)
200 feet to 1,000 feet (10 points)
Greater than 1,000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

9-23-96


Congress #4

Meridian O.I.

Sec. 35, T29N, R11W,

990' FNL - 790' FEL

90° E of N



clean closed
Abandoned pit
sandy soil

composite sample # 9609231030