



STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

May 31, 1990

Mr. Ron Headrick
Meridian Oil Inc.
P.O. Box 4289
Farmington, NM 87499

RE: Lackey #3, O-19-29N-09W
Grambling #5, P-27-29N-09W

Dear Ron:

Enclosed copies of the scheduled 1990 Bradenhead Tests on the referenced wells indicate casing failures. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

Charles Gholson
Deputy Inspector
NMOCD
District III

CG:sh



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 5-3 Operator Meridian Oil Inc

Lease Name Groubling Well No. 5 Location U P Sec 27 Twp 29 Range 9

Pressure (Shut-in or Flowing) Dwt Tubing SH Intermediate Casing 84 Bradenhead 84

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		<u>18</u>	Steady Flow <u>✓</u>	
10 Min.		<u>18</u>	Surges <u> </u>	
15 Min.		<u>12</u>	Down to Nothing <u> </u>	
20 Min.		<u>10</u>	Nothing <u> </u>	
25 Min.		<u>10</u>	Gas <u> </u>	
30 Min.		<u>10</u>	Gas & Water <u> </u>	
			Water <u> </u>	

If Bradenhead flowed water check description below:

Clear ✓
Fresh
Salty
Sulfur
Black

Remarks: Casing dropped to 24 PSI
when BH was opened

By [Signature]
(Position)