

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 87-076958
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 5, 19 56

Well No. h Bare is located 950 ft. from S line and 150 ft. from E line of sec. 25


24/32, Section 25 (Sec. and Sec. No.) T-24N, R-11W (Twp.) (Range) 10N, 10E (Meridian)
Acton Pictured Cliffs (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ground above sea level is 5611 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 2015. Top Pictured Cliffs formation 1951. Set 2005' of 5 1/2" casing at 2014' with 150 min. cement. Drilled cement plug October 24, 1956. Sealed hole dry. Tested for 2 hours with 500 lbs. pressure, pipe O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ATHE OIL & GAS COMPANY
Address P. O. Box 736
Farmington, New Mexico
By Joe C. Salomon
Title Drilling Superintendent