

District I
P.O. Box 1990, Hobbs, NM
District II
P.O. Drawer 00, Artesia, NM 88211
District III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OK
SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: CONOCO INC. Telephone: _____

Address: 3315 Bloomfield HWY. FARMINGTON N.M. 87401

Facility Or: HAMNER 2
Well Name _____

Location: Unit or qtr/qtr sec L sec 28 T 29N R 09W county SAN JUAN

Pit Type: separator _____ Dehydrator _____ other Blow Down Pit

Land Type: BLM ☒, State _____, Fee _____, other _____


Pit Location: Pit dimensions: length 8', width 8', depth 4'
(Attach diagram)

Reference: wellhead ☒, other _____

Footage from reference: 140'

Direction from reference: 203 Degrees _____ East North _____
of _____ West South ☒

Depth To Ground Water:
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)



Less than 50 feet	(20 points)
50 feet to 99 feet	(10 points)
Greater than 100 feet	(0 points) <u>0</u>

Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes	(20 points)
No	(0 points) <u>0</u>

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet	(20 points)
200 feet to 1000 feet	(10 points)
Greater than 1000 feet	(0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 8-16-99 Date Completed: 8-17-99

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description Of Remedial Action: SAMPLE TAKEN, Till Bottom of Pit
1' IN, Laydown Liver, set 25 Bbs steel TANK.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location CENTER OF P.T.
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths) Sample depth 6.5'

Sample date 8-11-99 Sample time 1239

Sample Results

Benzene (ppm) _____

Total BTEX (ppm) _____

Field headspace (ppm) 16

TPH 0.3

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 11-29-99

SIGNATURE

Judson Valdez

PRINTED NAME

AND TITLE Judson Valdez P.L.

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco Inc.	Project #:	707003-077
Sample ID:	BDP - Grab	Date Reported:	08-17-99
Laboratory Number:	F907	Date Sampled:	08-11-99
Chain of Custody No:	7103	Date Received:	08-13-99
Sample Matrix:	Soil	Date Extracted:	08-16-99
Preservative:	Cool	Date Analyzed:	08-16-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	0.3	0.1
Total Petroleum Hydrocarbons	0.3	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Hamner 2. OVM Reading 16. Hit Rock 2 1/2' In.


Analyst


Review

7103

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615


Lease Name: HAMNER #2 mV

Operator: LC Bob Williams Date: 8-16-99

Site Security
(Indicate North)



WFS
34-107
6m



SEP
234°S
95' FWH.
23'x13'x4'
ABANDON



BDP
203°S
140' FWH.
8'x8'x4'



Lease Name: Hamner 2

Federal/ Indian Lease No: SF 080245

CA No.: NA

Unit: L

Legal Description: Sect: 28 TP: 29N R: 9W

County: San Juan, NM

Load line valves :
Sealed during Production


Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM


8-11-99

Hammer 2



SEP

Time 1237 PPM 338
~~224~~ 204° S
95' FWH
ST-1242
Hit Rock Bed 2' IN



BDP

Time: 1236 PPM. 16
203° S
140' FWH.
ST-1239
Hit Rock Bed 2.5' IN.