

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan, N.M.
Lease No. 078931-1
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<u>Casing Report</u> X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 22, 1960

USA Glenn H. Callow
Well No. 10 is located 1770 ft. from XXS line and 1870 ft. from XXW line of sec. 27
SW 1/4 of Section 27 (1/4 Sec. and Sec. No.) T20N (Twp.) R13W (Range) W06M (Meridian)
Totah Callow (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation of the derrick floor above sea level is 5356 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate casing jobs, cementing points, and all other important proposed work)

We wish to report the running of surface casing as follows:

1. Drilled 12 1/8" hole to 146'.
2. Ran 132' 8 5/8" OD 20# J-55 STAC casing set at 145'.
3. Cemented with 75 ex regular cement, 3% CaCl₂ and circulated to surface. Plug down 5:30 a.m. 11/12/59.
4. WOC 24 hrs. Riggled up and pressure tested casing at 600 psi for 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tennessee Gas Transmission Company

Address P. O. Box 1714

Durango, Colorado

By R. E. Walker **R. E. Walker**

Title District Production Superintendent

